

# Oil Field Environmental Incident Summary

**Incident:** 20160318125822      **Date/Time of Notice:** 03/18/2016 12:58

**Responsible Party:** CONTINENTAL RESOURCES, INC.

**Well Operator:** CONTINENTAL RESOURCES, INC.

**Well Name:** SACRAMENTO 2-10H

**Field Name:** BROOKLYN

**Well File #:** 23020

**Date Incident:** 3/18/2016      **Time Incident:** 11:35

**Facility ID Number:**

**County:** WILLIAMS

**Twp:** 155

**Rng:** 98

**Sec:** 10

**Qtr:**

**Location Description:**

**Submitted By:** Timothy Ilse

**Received By:**

**Contact Person:** Jacob Renne  
PO BOX 268870  
OKLAHOMA CITY, OK 73126

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Equipment Failure

**Release Contained in Dike:** Yes - Within Dike

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	5	Barrels	5	Barrels		
<b>Brine</b>	2	Barrels	2	Barrels		

**Other**

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

None

**Areal Extent:**

N/A

**Potential Environmental Impacts:**

Well site soil

**Action Taken or Planned:**

Remove all visibly contaminated material and replace with clean-fill.

**Wastes Disposal Location:** R360

**Agencies Involved:** Notified John Rumppe @ 12:40 pm on 3/18/2016

**Updates**

---

**Date:** 3/18/2016    **Status:** Reviewed - Assigned to Other Agency

**Author:** O'Gorman, Brian

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release, due to equipment failure, remained within diking according to the report. NDIC retains oversight.